



DriTac - MCS 7000 Concrete Moisture Control System Two-Part Epoxy

DriTac Concrete Moisture Control System reduces the transmission rate of moisture vapor within any concrete subfloor (up to 12 lbs) to levels accepted by most wood flooring manufacturers. The DriTac System consists of a two component epoxy, which is mixed together to form a coating that is applied to the surface of the concrete subfloor.

When used in conjunction with DriTac 7600 and DriTac 7500 Urethane Adhesives, DriTac Concrete Moisture Control System is fully-warranted (see back for details). It dries quickly and has low odor. DriTac MCS also helps reduce the potential for mold and mildew growth caused by subfloor moisture.

DriTac Concrete Moisture Control System provides the professional installer with a productive and economical system designed to reduce concrete subfloor moisture for wood flooring installations.



- TWO-PART EPOXY
- REDUCES MOISTURE VAPOR TRANSMISSION
- SOLVENT FREE
- EASY TO INSTALL
- EASY CLEAN-UP WHEN WET
- SAFE FOR THE ENVIRONMENT
- ENHANCED WARRANTY

DriTac - MCS 7000 **Concrete Moisture Control System** **Enhanced Warranty**

DriTac warrants to its direct purchaser for resale that, for so long as Purchaser's customer owns the home for residential applications, or for five years from the date of installation for commercial applications, engineered wood flooring products covered by a valid subfloor moisture warranty that are installed with DriTac 7600 and DriTac 7500 Premium Urethane Wood Flooring Adhesives on a concrete subfloor that has been treated with DriTac Concrete Moisture Control System, will be free of the following moisture related problems due to moisture from the concrete subfloor: cupping, buckling, surface discoloration and release of bond to the subfloor. In addition, DriTac warrants that the (product) DriTac Concrete Moisture Control System will not promote or aid in the growth of mold or mildew.

If the purchaser believes that the above warranty has been breached, Purchaser must contact DriTac at 1-800-394-9310. Purchaser must provide its name, address, telephone number, address of the installed Product, name of specific product used, confirmation of date of product purchase, name and address of installer of the Product, results of calcium chloride moisture test performed prior to installation and a statement of complaint regarding the product. At DriTac's request, Purchaser shall arrange access to the premises where the Product was installed to allow DriTac or its agent to inspect the installation and shall make available, reasonable amounts of the affected flooring and /or Product for testing and inspection. DriTac may require verification of existing subfloor moisture conditions at the affected site by way of a calcium chloride moisture test. In the event DriTac or its agent determines that the above warranty has been breached, upon DriTac's request, Purchaser will obtain and submit three written estimates from reputable flooring installers regarding the cost of repairs. DriTac will approve one estimate and authorize Purchaser to proceed with the repairs by the approved installer. DriTac reserves the right to refuse any estimate and to identify acceptable installers. It is a condition of obtaining warranty performance that cost of repairs be approved in writing by DriTac prior to the start of the repairs. DriTac will reimburse Purchaser (one time) for the actual cost to repair or replace the affected area or areas of the installed wood flooring by the approved installer.

Exclusions From Coverage

The warranty does not apply if: (1) all instructions regarding preparation for installation and use of the engineered wood flooring products, DriTac 7600 and DriTac 7500 Premium Urethane Wood Flooring Adhesives, and DriTac Concrete Moisture Control System are not followed; (2) the DriTac Concrete Moisture Control System is used for below grade installation; (3) proper job site pre-inspection, installation and maintenance procedures are not followed; (4) the concrete subfloor is not clean, flat, free of debris and contaminants and structurally sound; (5) the concrete subfloor is not free of visible moisture including darkening of the concrete, standing water and condensation, and/or moisture content of the concrete becomes greater than 12 lbs. per 1,000 sq. ft. over 24 hours, per calcium chloride moisture test; (6) the property of the installation does not have proper drainage; (7) moisture related problems are related to flooding, leakage, topical moisture, improper ventilation, improper maintenance, or cracks in the subfloor or foundation; (8) problems arise due to in the wood flooring, or misuse or abuse. In addition, the product is not intended for mold or mildew abatement.

Limitations

To the extent permitted by law, the obligations set forth above are DriTac's sole obligations and the purchaser's exclusive remedies and, except as set forth above, DriTac makes no other warranties concerning the Product. DRITAC DISCLAIMS AND EXCLUDES ALL OTHER EXPRESS WARRANTIES AND ALL IMPLIED WARRANTIES INCLUDING WITHOUT LIMITATION THE IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE CONCERNING THE PRODUCT. DriTac's obligations shall be Purchaser's sole and exclusive remedy against DriTac for any liability with respect to the Product whether any claim for recovery is based upon or arises out of the theories of contract, negligence, tort (including strict liability) or otherwise and that IN NO EVENT SHALL DRITAC BE LIABLE FOR ANY INCIDENTAL OR CONSEQUENTIAL DAMAGES, including, without limitation, loss of income, loss of time, loss of sales, claims asserted by Purchaser's customers, injury to personal property or injury to any person. This warranty is made only to the original Purchaser and is not transferable.

For more information or to find a DriTac distributor nearest you call

DriTac Adhesive Group at 1-800-394-9310